



TRITON 3D

Stratasys Compatible 3D Printing Filament

Fortus® Build Tip Compatibility Chart

Printers		Stratasys Fortus® 360mc, 380mc, 380CFE, 400mc, 450mc, 900mc, F900								
Tip Size		T10	T12	T14	T16	T20	T40	T12SR20	T12SR30	T12SR100
Model Materials	ABS	X	X		X	X				
	ABSi	X	X		X	X				
	ESD ABS		X		X					
	CF ABS				X	X				
	ASA	X	X		X	X	X			
	Nylon 6			X		X				
	Nylon 12		X		X	X				
	CF Nylon 12					X				
	PC/ABS		X		X	X				
	FR PC/ABS		X		X	X				
	PC		X		X	X				
	PC ISO		X		X	X				
	ESD PC		X		X	X				
	Ultem 9085				X	X				
	Ultem 1010			X		X				
	ESD Ultem 1010			X		X				
	PPSU				X	X				
Support Materials	SR20 Support							X		
	SR30 Support								X	
	SR35 Support								X	
	SR100 Support									X
	ABS Support (BAS)				X				X	
	PC Support (BAS)				X					
	9085 Support (BAS)				X					
	1010 Support (BAS)				X					
	PPSU Support (BAS)				X					

T20B = Support tip for ASA when printing a T40A on a F900/900mc with SR30/35

T20C = CF PA12, CF ABS

T40A = ASA on F900/900mc only

SR = Soluble Support

BAS = Break Away Support (Not Soluble)