


Eje X
Eixo X
X axis
Axe X
X-Achse
Asse X
Ось X



1



x1
M6 x 40



x1
M3

x2
M5


x3
M6




x4
4A














1A



2A



3A



2



x2
M3 x 8



x2
M3



Allen 2.5


x3
4A





x2
6A



7A












5A



M3 x 8
Allen 2.5

M3





3



x2

M3 x 8

x3

M3 x 18

x1

M3 x 25




x3

M3



Allen 2.5


Allen 2




11A




8A



9A




10A




1B




12A




M3







M3



M3 x 18
Allen 2.5







4



x1
M4 x 20



x1
M4



Allen 2.5

Allen 3




13A



14A



x4
1B



1

2

