


Eje Z
Eixo Z
Z axis
Axe Z
Z-Achse
Asse Z
Ось Z



5



x16
M3 x 8

x2

M3 x 18



x2
M3



Allen 2.5

Allen 2


x2

15A



x2

8A




x2

22A




x2


23A




21A




16A




17A




7A



18A



19A



20A

